

SPROCKET ORIENTATION

Gates Carbon Drive front sprockets have been designed for a specific mounting orientation to properly display the sprocket branding. There is a small lobe on the internal diameter of every front sprocket that should be located directly behind the crank arm.

Figure 1: Tab mounting location for correct sprocket orientation.

