



May 2022

BOSCH DESIGN COVER REQUIREMENTS FOR MY23

The following BES3 Bosch drive systems have interference with Gates Carbon Drive belt systems starting in MY23:

| | |
|--|-------------------|
| MY23 Active Line | BDU310 / BDU330 |
| MY23 Active Line Plus | BDU350 / BDU380 |
| MY23 Performance Line / Performance Line Sport | BDU336Y / BDU338Y |

Gates recommends customers specify the previous generation MY22 (BES2) Performance Line design covers shown below.

| | |
|--|--------------|
| Design Cover Performance Line Front (Black) | 1270.015.251 |
| Design Cover Performance Line Right (Black) | 1270.015.252 |
| Design Cover Performance Line Left (Black) | 1270.015.253 |
| Fixing Screw for Design Cover M4x53.5 for BDU3YY | 1270.016.420 |
| Fixing Screw for Cable Protector M4x10 | 1270.016.431 |
| Logo Bezel - Specify Bosch Bezel Appropriate to System | |

When ordering BES2 Performance Line covers, please work with your Bosch representative to discuss planned volume of BES2 covers needed for additional model years, to ensure continued production support.

Note that the Bosch Connect Module (BCM) cannot be located inside the BES2 cover. If integration with the BCM is desired on the drive systems listed above, custom designed covers will be required.

For questions on integration, please contact Gates at info@carbondrive.net